

ELECTRICAL SAFETY RECALL



Ariston and Indesit Domestic Tumble Dryers sold in Australia from April 2004

MODELS: ASL70CX(AUS), ASL700CX(AUS), AQCF851BU(AUS), TCF87B6H1(AUS), AQC8BF7T1(AUS), AS60VX(AUS), IS60V(AUSA), AS600VX(AUS), IDV65(AUS), TVF75C6H1(AUS), IDVA735X(AUS)

DEFECT: There is potential for lint/fluff to dislodge from the rear drum seal, fall near the dryer heater and become ignited.

HAZARD: If the dislodged lint/fluff is significant in mass and density, the ignited lint/fluff may result in flames that could lead to property damage.

WHAT TO DO: Consumers should check if their appliance is potentially affected and if so, contact the Australian distributor, Arisit, so that arrangements can be made to modify the appliance at no charge. In the meantime, consumers should not leave appliances unattended whilst operating. Consumers should also carry out proper cleaning and maintenance, as outlined in the user manual.

CONTACT DETAILS: For more information about the recall, consumers are invited to visit the dedicated site <http://www.indesithotpointsafety.com> or contact Arisit on 1300762219.

See www.recalls.gov.au for Australian product recall information.